WALL BRACKET

XERO Linear Lighting Systems

1. Suitable Mounting Surface
2. Wall Bracket slide bolt
3. Part A bracket factory mounted on Luminaire
4. Part B bracket for fastening onto mounting surface
5. Holes for mounting fasterners
   (Note: Installer to select appropriate fastner)
6. Luminaire

---

1 Identify all parts

1) Luminaire with Part A brackets fixed
2) Slide bolt x 2 (per bracket)
3) Part B of bracket for fasterning to mounting surface
4) suspension plan

Determine mounting location

3 Determine required positioning of the luminaire on wall

4 Drill hole for power entry

Position brackets Fix with appropriate fastners at premeasured height

5 Connect luminaire to power before positioning on brackets

6 lower on to wall brackets using the cylindrical threaded fasteners as guides

7 Place luminaire in to position then fix with two screws per bracket

8 Check that the unit is level

XERO Linear Lighting Systems